

# ERGOCUT SW 115

# AUTOCUT SW 115P



PB0015	6m	Central	1


PB0017	6m	Central	1

BW0162	joint	10
BW0174	nut	1
BW0214	washer	10
BW0265	ring	10
BW0311	cable support	1
BW0328	back box	1
BW0329	cable protection	1
BW0340	trigger	1
BW0375	red Plasma handle	1
BX0020	trigger	10
BX0125	pilot arc cable 2.5 mm <sup>2</sup>	(m)
BX0140	cable 2x0.50 Ø5.2	(m)
CV0011	stand off guide	10
CV0021	carriage	1
CV0022	circle attachment	1
CV0098	electrode wrench SW115	1
CV0099	flowmeter SW115	1
EA0018	screw M4x6	50
EA0053	screw M4x4	50
EA0064	screw 3.9x16	50
EA0127	o ring Ø 20.63x2.62 Viton	10
EA0137	o ring Ø 7x2 Viton	10
EA0203	o ring Ø 22x2 red	10
EA0221	o ring Ø 14x1.78 red	10
EA0236	screw Ø 3x12	10


EA0282	d.h. clamp Ø 9.5	10
EA0313	spring	10
EA0374	spring	1
FA3020	quick connector	10
FE1132	gas hose+quick conn.	1
FH0884	water tube	2
FH0885	pivot assembly	2
FY0041	Plasma conn. (m)	1
PC0128	nozzle	2
PD0120-10	Ø 1.0 tip	10
PD0120-12	Ø 1.2 tip	10
PD0120-14	Ø 1.4 tip	10
PE0115	diffuser	2
PG0008	torch head	1
PG0009	torch head	1
PH0057	6m - 1/4G	1
PH0058	6m - 1/4G	1
PH0102	power cable 6m 1/4G	1
PH0219	6m - Shield	1
PR0121	electrode Hf	10
PT0024	kit Plasma conn.	1
QB0048	EPDM Ø26x28	(m)
QB0161	shield	(m)
TP0061	black handle metallic	1
TP0111	complete handle	1

**XXXX-XX** STANDARD CONSUMABLES IN RED


COMPLETE TORCHES    CONSUMABLES    CONNECTORS    SPARE PARTS




# ERGOCUT SW 115



	<b>NO HF</b>		6 m		1 m	1.1 Kg
V <sub>peak</sub> X100%	500 110A		4 bar		30 l/min	
	2+4 bar		1.4 l/min		25+30 mm	



# AUTOCUT SW 115P



	<b>NO HF</b>		6 m		1 m	1.2 Kg
V <sub>peak</sub> X100%	500 110A		4 bar		30 l/min	
	2+4 bar		1.4 l/min		20+25 mm	