






PCH/M-40 Pak Master 50XL Plus


4

5



11

10

9

8

7

6

Pos.	Part no.	Ref. no.	Description	PU
N/S	441P884018	2-5035	Hand torch PCH/M 40 cpl. with 25' (7.5 mts) cable	1
N/S	441P88401E	2-5036	Hand torch PCH/M 40 cpl. with 50' (15 mts) cable	1
N/S	441P884A18	2-5039	Machine torch PCH/M 40 cpl. with 25' (7.5 mts) cable	1
N/S	441P884A1E	2-5040	Machine torch PCH/M 40 cpl. with 50' (15 mts) cable	1
1	441P884950	9-8055	70° Hand torch head PCH/M 40	1
2	365P884001	8-0533	O-Ring	20
3	380P200398	9-8059	Handgrip complete with microswitch	1
4	441P884949	9-8053	180° Machine torch head PCH/M 40	1
5	441P884948	9-7833	Machine handle	1
6	441P884669	9-6506	Electrode - Hf (long life)	10
7	441P884676	9-6507	Gas Distributor (long life)	10
8	441P884678	9-6501	Tip - Drag (long life)	10
9	441P884677	9-6500	Tip - Standoff (long life)	10
	441P884947	9-6502	Tip - Gouging 1.2mm	10
10	441P884666	9-6003	Shield Cup - Std	10
11	441P884667	9-6004	Shield Cup - Crown (requires 441P884666)	10
N/S	316P408158	4-0815	Air and power cable 25' (7.5 mts) - Hand torch	1
N/S	316P40816E	4-0816	Air and power cable 50' (15 mts)- Hand torch	1
N/S	316P428978	4-2897	Air and power cable 25' (7.5 mts) - Machine torch	1
N/S	316P42898E	4-2898	Air and power cable 50' (15 mts)- Machine torch	1

CIRCLE CUTTING ATTACHMENT: See page no. 17